

Perfect Matte Melamine Cutting & Maintenance Instructions

Edge Trimming

Due to the production process, 15mm must be trimmed from all the edges of the panel material prior to subsequent processing. Trimming must take place for all panel thicknesses and all material. Surface defects in this area do not constitute grounds for complaint. Edge trimming must be taken into consideration before placing an order.

Maintenance and Cleaning Instructions

Perfect Matte Melamine surface is protected with a PE protective film (transparent film). After removal of the PE protective film, the surface is ready for daily use. Additional polishing is not necessary. A mild soap solution is sufficient for cleaning.

Important: The use of abrasive cleaning and scouring agents can result in damage. Do not use cleaning agents which contain alcohol as they are abrasive or corrosive.



0800 344 112 | sales@plymasters.co.nz | plymasters.co.nz

